

Measurement

			page
1.	Measurement Disturbance Immunity		
1.1	Development System Disturbance Immunity	E 1	2
1.2	Magnetic Field Probes	S 2	5
1.3.11-13	MINI-Burst Generator set	P 1	6
1.3.14	E-Pulser	P 23	9
1.3.15-16	B-Pulser, trigger	P 11t / P 12t	10
	<i>Accessories for generators under EN 61000-4-4</i>		
1.4.11-12	Field Source sets	H 2 / H3	11
1.4.13	Burst Transformer	PT 4	14
	<i>Test- and measuring devices</i>		
1.5.11-40	Optical Signal Acquisition (1/2/4 channels)	OSE 100 / 150 / 400	15
1.6.11-33	Optical Fibre Probe analog (1/2 channels)	A 100 / A 200 / A 300	18
1.7.10-20	Field Bus Analysis	CAN 100 / LIN 100	21
1.8.10-40	Burst Detectors	BD 11 / 01B / 06B / 01E	23
2. - 3.	Measurement Radiated Emissions		
2.1.0	Near Field Probe set (H field) activ	MFA 01 / MFA-optional	25